



LAND CORNER RECORD

Index: T5	Corner: 1/4 corner between Section 29 & 30	State of Indiana - Hoosier National Forest		
Section: 29/30	Township: 7N	Range: 1E	P.M.: 2nd	County: Monroe
Coordinate:	Lat./N: +/-1371719.7	SEE NOTE BELOW	Lon./E: +/-3134842.7	SEE NOTE BELOW
			Datum:	NAD83(sft)

CORNER HISTORY: (Chronological history of corner)				
1.) Date of Survey:	Surveyor:	Monument:	Recording Information:	Monument Photograph:
11/29/1978	K.Anderson	BRASS CAP	USFS Record	
Reference Objects:	Species:	Diameter:	Bearing:	Distance:
	Black Oak	16"	N 08° W	32.4'
	Black Oak	9"	S 62° W	22.1'
Evidence Found:	Red post 4' S. of IP, replaced rock 2"x12"x16"; IP 14" above ground with rock pile around. East aspect side hill.			
Monument Found:	3" diameter FS monument-steel pipe with a brass cap standing 18"			
2.) Date of Survey:	Surveyor:	Monument:	Recording Information:	
2/3/2010	Robert J. Stone	BRASS CAP	USFS Record	
Reference Objects:	Species:	Diameter:	Bearing:	Distance:
	B. Oak	24"	N 06° W	32.3'
	S. Oak	15"	S 63° W	22.5'
Evidence Found:	A 27" diameter black oak with a Land Survey Marker sign and a Monroe County Surveyor Marker tag is 7.3' S 65° E.			
Monument Found:	3" diameter FS monument-steel pipe with a brass cap standing 18"			

ACCESSORIES: Bearing and distance from monument to witness object				
Reference Objects:	Object or Tree Species:	Diameter:	Bearing:	Distance:
	B. Oak	24"	N 4° W	32.40'
	B. Oak	15"	S 67° W	22.36'
	Maple	12"	N 51° W	19.30'
Monument Found or Set:	Found 3" dia. steel pipe with a 3" brass disk, 1.5' above grade.			

MONUMENT SKETCH	NARRATIVE REFERENCE:
	The monument is a 3" dia. steel pipe with a 3" brass disk, 1.0' above grade (disk is rotated 135° counter-clockwise), located approximately mid slope on an east facing slope, approximately 600 feet south of the Southern Point Campground road. A 27" diameter Black Oak with a Land Survey Marker sign and a Monroe County Survey marker tag is 7.45 feet S 65° E. Walk in campsite #68 is to the northwest on top of the ridge approximately 350 feet. COORDINATE NOTE: The coordinates shown hereon were collected using a resource grade Trimble GEO XT unit as noted on Survey #2 noted above. The horizontal precision was 3.2 feet.

SECTION DIAGRAM	PERPETUATION RECORD:
 Corner Location = ●	Monument was found undisturbed per the 2010 Land Corner Record. Two existing bearing trees were remarked. One new bearing tree was established.
Section: 29/30	Prepared By: BRG #7308
	Date: 12/27/2012

Approved by SRB 2-26-2013

Index: T-5 Corner: ¼

Twnshp: 7N Range: 1E

LAND CORNER RECORD

Section: 29/30 2nd P.M. County

Monroe

State of Indiana
Hoosier National Forest

POLK-E19

EXISTING SURVEYS

Original Government Survey

Year Surveyed:	1814	By:	Arthur Henrie
----------------	------	-----	---------------

Original Survey Evidence Found

Date of Search:	Sept. 28, 1854	By:	James w. Spencer
-----------------	----------------	-----	------------------

Original Monument:	Wood post
--------------------	-----------

Monument Found:	Eastern ½ mile post
-----------------	---------------------

Species	Diameter	Bearing	Distance
B. Ash	10"	S19°E	3 links
Sugar	8"	S39°W	17 links

Species	Diameter	Bearing	Distance
NOT	STATED		

Subsequent Corner Restoration

Where Filed or Recorded:	Hoosier National Forest – Bedford, IN		
Book:	Page:	Date:	11/29/1978
Monument Set:	3" diameter pipe monument with a brass cap		

Evidence of Subsequent Corner Restoration Found

Year Searched:	10/10/2012	By:	B.Stone
Monument Found	3" diameter FS monument with a brass cap stamped as shown and standing 18" above ground.		

Species	Diameter	Bearing	Distance
B.Oak	16"	N08°W	32.4 Ft.
B.Oak	9"	S 62° W	22.1 Ft.

Species	Diameter	Bearing	Distance

OTHER EVIDENCE

Describe corner loc. relative to nearby features & dir. to corner location; note fences, roads, etc.	Sketch of Monument
The corner monument is mid slope on an east facing slope approximately 600 feet south of the Southern Point Campground road. A 27" diameter Black Oak with a Land Survey Marker sign and a Monroe County Survey Marker tag is 7.3 feet S65°E. Walk in campsite #68 is to the northwest on top of the ridge approximately 350 feet. The monument and Bearing trees have recently been repainted by Bledsoe Riggert & Guerrettaz under contract. See the Task Order survey file for further information. The coordinates shown below were collected using a resource grade Trimble GeoXH unit. The horizontal precision was 0.7 feet.	


PERPETUATION RECORD

Photographs of the monument and vicinity:

View to the northwest



2012. 10. 10

Corner Diagram		Accessories: Describe BTs & witness objects established to perpetuate existing evidence.					
		Bearing Trees repainted and tagged:					
		S. Oak		Maple		B. Oak	
		12"		12"		24"	
		S 63°W		N 55°W		N 06°W	
		22.5 Ft.		19.6 Ft.		32.3 Ft.	
Corner Recordation:				Certificate Prepared:			
Filed and Recorded in				Date:			
County records:							
Book:				Page:			
Section:		29		Indiana State Plane Coordinates:		N. 1371719.624 E. 3134842.431	
				Edited By: Robert J. Stone		Date Created: 10/19/2012	

Index: T-5 Corner: 1/4

LAND CORNER RECORD

State of Indiana
Hoosier National ForestTwonshp: 7N Range: 1E Section: 29/30 2nd P.M. County

Monroe

EXISTING SURVEYS

Original Government Survey

Year Surveyed:		By:	
Original Monument:			
Species	Diameter	Bearing	Distance

Original Survey Evidence Found

Date of Search:		By:	
Monument Found:			
Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Where Filed or Recorded:			
Book:	Page:	Date:	
Monument Set:			
Species	Diameter	Bearing	Distance


Evidence of Subsequent Corner Restoration Found

Year Searched:	2/3/2010	By:	B. Stone
Monument Found	3" diameter FS monument-steel pipe with a brass cap standing 18"		
Species	Diameter	Bearing	Distance

OTHER EVIDENCE

Describe corner loc. relative to nearby features & dir. to corner location; note fences, roads, etc.	Sketch of Monument
The corner monument is approximately mid slope on an east facing slope, approximately 600 feet south of the Southern Point Campground road. A 27" diameter Black Oak with a Land Survey Marker sign and a Monroe County Survey Marker tag is 7.3 feet S 65°E. Walk in campsite #68 is to the northwest on top of the ridge approximately 350 feet. The coordinates shown at the bottom were collected using a resource grade Trimble GEO XT unit. The horizontal Precision was 3.2 feet.	

PERPETUATION RECORD

Photographs of corner monument and vicinity:	
	

Corner Diagram	Accessories: Describe new BTs & witness objects established to perpetuate existing evidence.		
	Old Bearing Trees with healed over blazes: B. Oak 24" N 06°W 32.3 Ft. S. Oak 15" S 63°W 22.5 Ft.		
	Corner Recordation:		Certificate Prepared:
	Filed and Recorded in County records:		Date:
	Book:		Page:
Section: 30	Indiana State Plane Coordinates:	N. 1371719.668	E. 3134842.689
	Edited By: Robert J. Stone	Date Created:	2/12/2010

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 30

Township: 7 North


Range: 1 East

Corner ID: Polk E-19

Monument Description & Remarks: 3" Iron Pipe, 1.5ft above ground, with brass cap "1978 SO143". Survey Sign 4.5ft above ground at pt. B.

References On File: Legal Survey book 2 page number 217, Survey (1873), & LAND CORNER RECORD T-5 (1973), on file in Surveyor Office

RECOVERY TIE DRAWING
Field Book 37 Page No. 69




- A - 3" Iron Pipe with Brass cap
- B - S 66° E 6.51' to Survey Sign on 27" Black Oak
- C - S 69° W 21.70' to MAG nail in 14" Black Oak
- D - N 02° W 32.35' to MAG nail in 27" Black Oak

Not To Scale
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 25th day of January 2006.

Kevin P. Enright



Administered by the Monroe County Surveyor Review Board

Date: 8-14-2007

Index No. T-5
(Alphabetical - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 806-924T. 7N R. 1E Mer. N.F. Noos County Monroe State Ind.
Section 29 Corner common to sections 29 30 and

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed <u>1874</u>	Year of search <u>1973</u> By <u>K. Denton</u>
Original monument <u>Wood Post</u> (Wood post, stone, pile of stones, pipe, etc.)	Monument found <u>No</u>
Bearing Trees	Original Bearing Trees Found
Species <u>Hickory</u> <u>B. Oak</u>	Species _____
Diameter <u>10"</u> <u>18"</u>	Diameter _____
Bearing <u>N 71 E</u> <u>S 30 W</u>	Bearing <u>N 0 E</u>
Distance <u>27 lks</u> <u>12 lks</u>	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____	Year of search <u>1973</u> By <u>K. Denton</u>
Where filed or recorded _____	<u>Found stone. Area was marked with a fence from the south and wood intersected at the stone rock was 10" DBT was East of stone</u>
Monument _____ (Original, concrete post, iron rod, etc.)	
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____



Sketch

○ Corner ■ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

remnant stone of dug under it looking for evidence of orig. post. found none. From the looks of the undisturbed rocky (soap stone) ground under the monument stone I doubt that there ever was a post in the ground at this point. gff

Perpetuation Record

Monument and accessories established. Include brief description of area.

Established one BT to preserve point. Fence from East terminates in BT.

B Oak 18"
568 E
7.6 Ft.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

At time of search:

1. Did you have the record description?

Yes ☒ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. aerial maps3. Man hours spent in search 1 hr

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature K. Denton